




1





2




3




4




A X2




B X20



C X8



D X2




E X2



F X6




G X8



H X8















J X2




K X*





L X2




13



14



15




Muy importante: El mecanismo no funcionará si la pieza N no está montada en su posición correcta.




Very important: The mechanism will not work if part N is not mounted in its correct position.

Très important: le mécanisme ne fonctionnera pas si la pièce N n'est pas montée correctement.

16



17



18

